

Government of Bihar
Public Health Engineering Department
Water Quality Test Report
Division Name: Buxar

District :-Buxar

Sample Collected by :- Laxman Yadav, Buxar.

Date- 16.03.2026

Sl. No.	Block	Panchayat / Municipal Corporatio	Location of Source	Source Type	Parameters												Remarks
					pH	Turb.	EC	TDS	TH	Ca	Mg	Cl	Alka.	Fe	As	Total Coli.	
	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18
1	Rajpur	Dhansoi	De Meester, School Sisaundha Dera, Dhansoi.	Bore well	7.4	0.8	576	375	232	52	43.20	48	248	0.2	0.004	Negative	SAFE
UNIT						NTU	$\mu\text{mho/cm}$	mg/l	mg/l	mg/l	mg/l	mg/l	mg/l	mg/l	mg/l		
Desirable Limit*					6.5-8.5	1		500	200	75	30	250	200	0.3	0.01		
max.permissiable limit					NR	5		2000	600	200	100	1000	600	1.0	NR		

* BDL - Below detection limit.

* NR - Not relaxation.

(Signature)
Chemist
P.H.Division, Buxar

(Signature)
Executive Engineer
P.H.Division, Buxar

16/03/2026
अभियंता
लोक सेवा. प्र. बक्सर